



10/773880

Colc



A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS



BLAKELY SOKOLOFF TAYLOR & ZAFMAN

TELEPHONE (408) 720-8300
FACSIMILE (408) 720-8383
BSTZ_MAIL@BSTZ.COM
WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW
SILICON VALLEY
1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

LOS ANGELES, CA
ORANGE COUNTY/COSTA MESA, CA
SAN JOSE, CA
DENVER, CO
PORTLAND/BEAVERTON, OR
SEATTLE, WA

November 29, 2005

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450


Re: **CERTIFICATE OF CORRECTION**
U. S. Letters Patent No. 6,968,404
Issued: November 22, 2005
For: **OPTICAL DRIVE CONTROLLER WITH A
HOST INTERFACE FOR DIRECT
CONNECTION TO AN IDE/ATA DATA BUS**
Inventor: Verinsky et al.
Our File No. 003551.P006C3

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP


Daniel M. De Vos
Reg. No. 37,813

*Certificate
DEC 06 2005
of Correction*

EHT/keh
Enclosures

DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,404

DATED : November 22, 2005

INVENTOR(S) : Verinsky et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 17, at line 40, delete "(36h and" and insert --(36h) and in the ATAPI Drive Select Register, and--.

In column 18, at line 47, delete "SLBHO-3" and insert --SUBHO-3--.

In column 19, at line 42, delete "LRTBSY" and insert --URTBSY--.

In column 26, at line 16, delete "(20h0.3)" and insert --(20h.3)--.

In column 26, at line 19, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 7, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 21, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 25, delete "(22h0.2,1,0)." and insert --(22h.2,1,0)---.

In column 27, at line 57, delete "(20h0.4)" and insert --(20h.4)--.

In column 28, at line 60, delete "PDJAG" and insert --PDIAG--.

In column 28, at line 62, delete "HJRQ" and insert --HIRQ--.

In column 30, at line 53, delete "bufkr" and insert --buffer--.

In column 32, at line 15, delete "PDJAG" and insert --PDIAG--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,968,404

Certificate of Correction (PTO Form 1050)-Amended

DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,404

DATED : November 22, 2005

INVENTOR(S) : Verinsky et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 17, at line 40, delete "(36h and" and insert --(36h) and in the ATAPI Drive Select Register, and--.

In column 18, at line 47, delete "SLBHO-3" and insert --SUBHO-3--.

In column 19, at line 42, delete "LRTBSY" and insert --URTBSY--.

In column 26, at line 16, delete "(20h0.3)" and insert --(20h.3)--.

In column 26, at line 19, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 7, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 21, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 25, delete "(22h0.2,1,0)." and insert --(22h.2,1,0).--.

In column 27, at line 57, delete "(20h0.4)" and insert --(20h.4)--.

In column 28, at line 60, delete "PDJAG" and insert --PDIAG--.

In column 28, at line 62, delete "HJRQ" and insert --HIRQ--.

In column 30, at line 53, delete "bufkr" and insert --buffer--.

In column 32, at line 15, delete "PDJAG" and insert --PDIAG--.

MAILING ADDRESS OF SENDER

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,968,404

Certificate of Correction (PTO Form 1050)-Amended

DEC 6 2005